

BREATH ALCOHOL PROGRAM

JUN-8 2009

Complete this report in duplicate at the time of the regulis repaired. Send copy to Department of Health; retain original contents of the second copy to Department of Health; retain original contents of the second contents of the	ular monthly preventive malr inal in department file.	ntenance c	1.11	oo ontie Hi	
DATAMASTER \$N 950053				NSPECTION	
LOCATION OF INSTRUMENT (STREET AND CITY) 114 South Rollins Street		Centralia		изрестіби "	الما المنافض المنافظ ا
CHECKLIST: Place a check (<) to the left of each item if in observed values where determined.) Unchecked items mu	found to be satisfactory or it ust be corrected before using	operating Instrumen	within e t.	stablished limi	ts. (Write
☑ DIAGNOSTIC CHECK (PRINTOUT ATTACHED)					
☑ COMPUTER	☑ DETECTOR	·			
🛮 program	☑ FILTERS				
☑ HEATERS SAMPLE CHAMBER°C	🗹 QUARTZ STANDA	RD			
☑ FLOW DETECTOR	☑ CALIBRATION				
☑ PUMP HIGH SPEED	2 PRINTER				
☑ INDICATOR LIGHTS					
☑ TIME AND DATE	·				
SIMULATOR TEMPERATURE (34 °C ± 0.2°C) 34°C					
CALIBRATION CHECK - Run three tests using a standard solution. All three tests					
CALIBRATION CHECK - Run three tests using a standard solution. All three spread of .005 or less. Check the box corresponding t RECIRCULATION PUMP)  0.100% STANDARD - MUST READ BETWEEN 0.0956 0.040% STANDARD - MUST READ BETWEEN 0.0386	to the standard solution being				
CALIBRATION CHECK - Run three tests using a standard solution. All three tests of .005 or less. Check the box corresponding the RECIRCULATION PUMP)  O.100% STANDARD - MUST READ BETWEEN 0.095  0.040% STANDARD - MUST READ BETWEEN 0.038  (ONLY ONE STANDARD IS TO BE USED PER MAINTER	to the standard solution being		PRINTO		
CALIBRATION CHECK - Run three tests using a standard solution. All three tests pread of .005 or less. Check the box corresponding the RECIRCULATION PUMP)  0.100% STANDARD - MUST READ BETWEEN 0.0956 0.040% STANDARD - MUST READ BETWEEN 0.0386 (ONLY ONE STANDARD IS TO BE USED PER MAINTEREST 1 .101  TEST 2	to the standard solution being the standard solution being the stand 0.105% INCLUSIVE ENANCE REPORT)	ng used. (I	PRINTO	UT ATTACHE	
CALIBRATION CHECK - Run three tests using a standard solution. All three tests pread of .005 or less. Check the box corresponding the RECIRCULATION PUMP)  0.100% STANDARD - MUST READ BETWEEN 0.0950 0.040% STANDARD - MUST READ BETWEEN 0.0380 (ONLY ONE STANDARD IS TO BE USED PER MAINTE	to the standard solution being and 0.105% INCLUSIVE 1% and 0.042% INCLUSIVE ENANCE REPORT)  .101  REPORT, AND NUMBER OF	ng used. (F	PRINTO	UT ATTACHE	D) (USE
CALIBRATION CHECK - Run three tests using a standard solution. All three spread of .005 or less. Check the box corresponding the RECIRCULATION PUMP)  0.100% STANDARD - MUST READ BETWEEN 0.0956 0.040% STANDARD - MUST READ BETWEEN 0.0386 (ONLY ONE STANDARD IS TO BE USED PER MAINTEREST 1  TEST 1  PERFORM R.F.I. TEST (PRINTOUT ATTACHED)  NUMBER OF REFUSALS, SINCE LAST MAINTENANCE	to the standard solution being the standard solution being the stand 0.105% INCLUSIVE (100 and 0.042% INCLUSIVE ENANCE REPORT)  .101  REPORT, AND NUMBER OF	ng used. (F	PRINTO	UT ATTACHE	D) (USE
CALIBRATION CHECK - Run three tests using a standard solution. All three spread of .005 or less. Check the box corresponding the RECIRCULATION PUMP)  0.100% STANDARD - MUST READ BETWEEN 0.0956 0.040% STANDARD - MUST READ BETWEEN 0.0386 (ONLY ONE STANDARD IS TO BE USED PER MAINTER  EST 1	to the standard solution believed and 0.105% INCLUSIVE was and 0.042% INCLUSIVE ENANCE REPORT)  .101  REPORT, AND NUMBER OF the control of the tweether was made to restore the control of the control of the little and regulations.	TEST 3  F BREATH  1519) Fe the instruction on the contract of the contract on the contract o	TESTS  1 ument to	.101 IN EACH RAN (Over .19) o operate satist	GE AS  2 sfactorily rated
Run three tests using a standard solution. All three spread of .005 or less. Check the box corresponding the RECIRCULATION PUMP)  0.100% STANDARD - MUST READ BETWEEN 0.0956 0.040% STANDARD - MUST READ BETWEEN 0.0386 (ONLY ONE STANDARD IS TO BE USED PER MAINTED TEST 1  101  TEST 2  PERFORM R.F.I. TEST (PRINTOUT ATTACHED)  NUMBER OF REFUSALS, SINCE LAST MAINTENANCE FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS)  EFUSALS 1 (004) 1 (.0509) 3  ist any new parts and describe any alteration or modificated within established limits (use other side if necessary)  New EPROM Installed, New Chopper Motor Installed, New EPROM Installed, New EPR	to the standard solution believed and 0.105% INCLUSIVE was and 0.042% INCLUSIVE ENANCE REPORT)  .101  REPORT, AND NUMBER OF the control of the tweether was made to restore the control of the control of the little and regulations.	TEST 3  F BREATH  1519) Fe the instruction on the contract of the contract on the contract o	TESTS  1 ument to	.101 IN EACH RAN (Over .19) o operate satist	GE AS  2 sfactorily rated

### CERTÍFICATE OF ANALYSIS

MANUFACTURER AND SUPPLIER: RepCo Marketing, Inc.

LOT NUMBER: 08002

EXPIRATION DATE: October 13, 2010 at 11:59 p.m.

RepCo Marketing, Inc. certifies the following:

RepCo Marketing, Inc. manufactured, tested and supplied Lot Number <u>08002</u> of Alcohol Certified Solution for simulators. Random samples of said lot number were analyzed utilizing a gas chromatograph and found to contain <u>0.1209</u> gms/dl wt/vol ethyl alcohol in aqueous solution (i.e. ethanol).

The alcohol and distilled water used in the solution were found to be free of any interfering substance.

This solution will produce a vapor alcohol value of <u>0.100%</u> +/-3% when heated to 34 Degrees Celsius +/-0.2 Degrees Celsius in a simulator.

The date of manufacture for this lot number is <u>October 14, 2008</u>. The expiration date for this lot number is <u>October 13, 2010</u> at 11:59 p.m.

This document is a true representation of the original Certificate of Analysis.

Cecil B. Garner, President RepCo Marking, Inc. Face This Side Down - This Edge In First

**BAC DataMaster**Evidence Ticket

STATE OF MISSOURI CENTRALIA POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 950053 1 05/19/09

TESTING OFFICER:
HELM/NICHOLAS/L
OFFICER I.D.: 677
PERMIT NUMBER: 820118
EXPIRATION DATE: 03/31/10
MISCELLANEOUS DATA:

### --- SUPERVISOR MODE ---

BLANK TEST	.000	19:12
INTERNAL STANDARD	VERIFIED	19:13
EXTERNAL STANDARD	. 101	19:13
BLANK TEST	.000	19:14
EXTERNAL STANDARD	. 101	19:14
BLANK TEST	. 999	19:15
EXTERNAL STANDARD	. 101	19:15
BLANK TEST	.000	19:15

N = 3 SIM. = .1 AVG. = .101

tor Signature Historia L. 2208-02

Face This Side Down - This Edge In First

### **BAC DataMaster**Evidence Ticket

STATE OF MISSOURI CENTRALIA POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 950053 05/19/09

--- BREATH ANALYSIS ---

BLANK TEST .000 19:09
INTERNAL STANDARD VERIFIED 19:09
RADIO INTERFERENCE

Operator Signature Michaelach

Face This Side Down - This Edge In First

## **BAC DataMaster**Evidence Ticket

STATE OF MISSOURI CENTRALIA POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 950053 05/19/09 19:04

--- DIAGNOSTIC CHECK ---

COMPUTER:

OKAY

PROGRAM (04-07-2009):

OKAY

**HEATERS** 

SAMPLE CHAMBERS

50c

FLOW DETECTOR:

OKAY

PUMP

HIGH SPEED: .

OKAY

DETECTOR:

OKAY

FILTERS:

OKAY

QUARTZ STANDARD:

OKRY

CALIBRATION:

OKAY

PRINTER TEST

!"#\$%&'()\*+,-./0123456789:;<=>?&ABCDEFG HIJKLMNOPQRSTUVWXYZ[\]^\_\abcdefshijklmno parstuvwxyz{|}>+

Operator Signature Hickory

2208.0

# State of Missouri DEPARTMENT OF HEALTH





## NECTEDIAS FIELM

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s);

## DATAMASTE

for the determination of the sicoholic content of blood from a sample of expired (sixeciar) sir. Issued under the provisions of sections 577.020 through 577.041, RSMb 1988.

Osta 05/31/08
Number 8:20118

Expire 03/31/2010

(BELL) 1220-035-041

Time a soul

Director of State Politic Hautin Laboratory

Constitution of

H-400-H